

PT-UNI-MK INSTALLATION GUIDE

To mount your power supply you'll need:

- Scissors or Utility Knife Phillips Head Screwdriver Electric Drill with 1/8" (or 3mm) Drill Bit
- POWER SUPPLY (BOTTOM)

 1. Cut and install 2 strips of the included hook-and-loop tape (hook side only) to the bottom of your power suppply.









